Gear Ratios

The ratio chart below provides the final drive ratios.

Renthal Motorcycle Final Drive Ratios Chart												
^	TEETH IN GEARBOX CHAINWHEEL											
MORE ACCELERATION		10	11	12	13	14	15	16	17	18	19	20
	65	6.50	5.91	5.42	5.00	4.64	4.33	4.06	3.82	3.61	3.42	3.25
MORE	64	6.40	5.82	5.33	4.92	4.57						